22/133. b) Maintenance Report

i) **Bollards** - Borough Councillor Reilly met with a Design Out Crime Officer from Warwickshire Police to look at the security of the green against potential unauthorised encampments.

The findings were passed to the Parish Council as follows:

The concrete posts along Attleboro Lane are loose and can be easily removed, I would recommend that the knee height metal fencing be extended to cover this area.

The current bollards at the three entry points onto the green need to be upgraded to a stronger deterrent, I've attached a link to a bollard that would be fit for use.

Telescopic Bollards, Safety Post - Rhino Security Ltd. (rhinobollardsonline.co.uk)

Cllr Robinson attended the green following this recommendation and obtained the following photograph to show the current condition of the bollards.

Council to consider obtaining a budget quotation to decide whether to proceed and balance the level of risk to the authority against the cost of improved security.

ii) **Dog Bin Attleborough Lane** – To consider replacing the broken dog waste bin with a general waste bin instead as collection costs are paid to NWBC for Dog Bins, Village Caretakers empty standard bins. Dog waste can be placed in either. Derby Standard Litter Bin - 120 Litre: BX45G 2550 | Broxap £329 (EX VAT) plus carriage there are various options to consider such as alloy banding or to have a laser cut logo on the bin which would be at additional cost (price on application). Using the Parish Council logo on assets can help with raising a Council's profile and recognition within the community (costs in 2020 were £45 for a laser cut logo) Alloy banding can help the bin look better for longer, standard vinyl banding is prone to scratching (costs in 2020 were £60 for alloy banding.) Broxap are a reputable supplier of street furniture used widely by local authorities. K-Nine Post Mounted Dog Waste Bin: BX45G 2580-pm | Broxap A replacement dog bin would cost £165 for 40 litres or £175 for 60 litres plus carriage and we pay NWBC £142.68 per annum for each dog bin in the parish. Examples of alternative providers are Bollard, Litter Bin & Smoking Shelter Suppliers - Glasdon UK or Litter Bins | Street Furniture Direct

iii) **Kickboard Fence Repairs** – Hawkes Blacksmiths had been authorised to carry out repairs at a cost of £358 by the Clerk in conjunction with the members of the maintenance committee. The panel was to be removed by the contractor and repaired and resprayed at the workshop, and was expected to take a week to repair.

iv) **Pavilion Shed Locks** – To consider quote obtained to change the shed lock at a cost of £TBC

v) **Pavilion maintenance** – To consider quote obtained for custom cupboard to house modem and other wiring beneath the TV to make safe at a cost of £TBC

vi) **Goal Post Sockets –** Caretakers have reported socket covers going missing frequently, Council may need to purchase more socket covers and discuss with football teams who should be responsible for making sure these are in situ once goalposts are removed and to ask teams to check if they have any socket covers in kit bags etc.

vii) **Bus Shelter –** A WOCAG representative had requested an update on the replacement of the Birmingham Road Shelter at a previous meeting, no further update to report at present.

viii) **See-saw –** A resident had requested an update to the see-saw repairs as this had been taken away almost 12 months ago. Update provided that Council had looked at a replacement and had then looked at a wider play area refurbishment project.