Refusal of MOT test certificate

① Vehicle identification number

VF1FW57B550091430

② Registration number

② Country of registration

BT63PKV

GB

Make and model

RENAULT KANGOO

S Vehicle category

Mileage

N₁

66,044 miles

Fail

© Repair immediately (major defects)

- Brake pipe excessively corroded Nearside (Front to Rear) [1.1.11 (c)]
- Brake pipe excessively corroded Offside (Front to Rear) [1.1.11 (c)]

® Repair as soon as possible (minor defects)

• Windscreen damaged but not adversely affecting driver's view [3.2 (a) (i)]

Monitor and repair if necessary (advisories)

- Brake pipe corroded, covered in grease or other material Nearside Front [1.1.11 (c)]
- Brake pipe corroded, covered in grease or other material Offside Front [1.1.11 (c)]
- Brake hose has slight corrosion to ferrule Nearside Rear [1.1.12 (f) (i)]
- Brake hose has slight corrosion to ferrule Offside Rear [1.1.12 (f) (i)]
- Tyre slightly damaged/cracking or perishing Nearside Rear [5.2.3 (d) (ii)]

Date of the test

24.06.2024

3 Location of the test

MARSH LANE, WATER ORTON, BIRMINGHAM, B46 1NW

Testing organisation and inspector name

V106300 BIRMINGHAM MOTORIST CENTRE LIMITED J. M. HOLMES

MOT test number

3860 7666 4242

To find out about retests, or if you disagree with the test result, see the fees and appeals poster at the vehicle testing station. Alternatively, visit www.gov.uk/getting-an-mot

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000.

Find out about the vehicle's MOT history at www.gov.uk/check-mot-history

J. Horry

Driver & Vehicle

Standards

Agency

Issuer signature